

Under Review Notification

Raised By: VANESSA MOREL
Date: 19.09.23

Product #: DART TOOLING EUROCOPTER

Product Name: REPLACEMENT BUSH OF REAR BLAD TOOL

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBE350A93-1280-00	RBE350A93-1280-00 REV 2	Y	Y	N	Y	N	N	N	19-915	SEE BELOW

Supercell

Description of Issue:

RBE350A93-1280-00 rev 2: All subcomponents and parts need to be put under review as well.

Tool is wrong ; customer issue

Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene